






紧固件清单

- | | | | |
|--|---------------|--|-------------------------|
| | 外六角M1.6-4 × 2 | | M1.6六角螺母 × 2 |
| | 外六角M2-6 | | M2自锁螺母 |
| | 外六角M2-4 × 8 | | φ1.2 E卡 × 5 |
| | 半圆头M2-3 × 12 | | 拉簧 直径2.5×线径0.3×长度13 × 3 |
| | 半圆头M3-6 × 4 | | |



①

②



不要过紧拧紧
Don't Over Tighten/Strug Tight
确保零件安装后能自由旋转
Ensure Free Rotation

③


外六角M1.6-4 × 2

M1.6六角螺母 × 2


φ1.2 E卡



C1




C2



④




拉簧 直径2.5×线径0.3×长度13 × 3




⑤




外六角M2-4 × 8



D1 × 2





D2



⑥



半圆头M2-3 x12



M-7702

⑦



半圆头M3-6 x4

